
Munro 6 Drawer Dresser

ASSEMBLY INSTRUCTIONS

KEEP ALL PACKAGING MATERIALS UNTIL YOU HAVE VERIFIED ALL COMPONENTS AND PARTS.

- 1. Carefully place the dresser on its back on a clean, flat surface, ensuring that it will not get damaged.
- **2.** Bolt the legs to the corners of the metal skirt by lining up the holes and using the hardware provided in the order shown below. Tighten with the provided Allen wrench (**D**)
- 3. Attach the center support leg by threading it into the base under the cabinet.
- 4. Install the anti-tip hardware to secure the dresser to the wall.

Clean all surfaces with a damp, soft cloth. Do not use abrasive cleaners.



Wood Care - Rubio Monocoat


Select designs feature wood that is finished with Rubio Monocoat - an environmentally friendly, oil-based protector designed to highlight the beauty of natural wood. These designs require special care to ensure they maintain their appearance. Please read and follow the directions below.

Shrinking, Cracking, Warping:

Wood is very susceptible to changes in the humidity of its environment, which causes it to expand and shrink. Climate control will minimize this. A level of 40%-55% humidity with an ideal temperature of 70-72 degrees Fahrenheit should be maintained.


Preventative Measures:

Oil finished, wood products are naturally porous, which means placemats and/or tablecloths must be used whenever possible to preserve the look and feel of the wood surface. Spills must be cleaned immediately to prevent discoloration and/or permanent damage.




Temperature:

Do not put any extremely hot or cold food items/ beverages in direct contact with the wood surface as this may cause marking or damage to the finish.



Cleaning:

Only use cold water and a soft mircofiber cloth to clean food, dust or spills. Wipe in the direction of the wood grain. Do not use abrasive cleaning products. Do not use household cleaning products that contain degreasers as they remove the finish from the wood over time.



Sunlight:

Ensure that your table is not exposed to direct sunlight for extended periods of time. This may cause discoloration as well as shrinking and cracking as the surface temperature changes throughout the day.

